COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway, Denver, Colorado 80203


ADDITIONAL PAGES:

YES

X NO

	NOT FOR FIELD US	SE
Eligible	1	Nominated
Det. Not		Certified Rehab.
	Date	

HISTORIC BUILDING INVENTORY RECORD		L	Date
PROJECT NAME: Littleton Historic Buildings Survey 1997 (#97-01-082)	COUNTY: Arapahoe	CITY: Littleto	STATE ID NO.: 5AH281 TEMPORARY NO.: N/A
CURRENT BUILDING NAME: U.S. Post Office-Littleton	OWNER: U.S. Postal Service 5753 S. Prince St. Littleton CO 80120 TOWNSHIP 5S RANGE 68W SECTION 17 SE 1/4 SE 1/4		
ADDRESS: 5753 S PRINCE ST Littleton, CO 80120			
HISTORIC NAME: U.S. Post Office-Littleton	U.S.G.S. QUAD NAME: Littleton, Colo. YEAR: 1965 (r. 1994) X 7.5' 15'		
DISTRICT NAME:	BLOCK: 8 LOT(S): 1-5 ADDITION: LITTLETON ORIG. TOWN YR. OF ADDITION: 1872		
FILM ROLL NO.: 97-12 BY: Roger Whitacre NEGATIVE NO.: 6	LOCATION OF NE		DATE OF CONSTRUCTION: ESTIMATE: ACTUAL: 1939 SOURCE: Litt. Indep., 8-20-48 USE: PRESENT: Post Office
			HISTORIC: Post Office CONDITION: X EXCELLENT GOOD FAIR DETERIORATING
			EXTENT OF ALTERATIONS: MINOR X MODERATE MAJOR DESCRIBE: Large addition on north. CONTINUED YES X NO
STYLE: Colonial Revival		STORIES:	ORIGINAL SITE X MOVED DATE(S) OF MOVE:
MATERIALS: Brick, Wood		SQ. FOOTAGE	: NATIONAL REGISTER ELIGIBILITY
ARCHITECTURAL DESCRIPTION: One-story brick post office building. Original portion of building has side gable roof, while addition on north has flat roof. Stone cornice with dentil molding. Gable faces clad with lap siding and have dentil molding and half- fan windows. Center cupola topped by weather vane has wood base, metal roof, 6/6-light double-hung windows, and fluted pilasters. Central double door entrance on east flanked by wood columns supporting frieze; arch above door			INDIVIDUAL: YES X NO CONTRIBUTING TO DISTRICT: YES NO LOCAL LANDMARK DESIGNATION: NO NAME: DATE:
ornamented with cast bronze eagle. Iron light posts flank stairs leading to entrance. Stone water table; window well and stairs to basement door on south. Windows are 12/1-light double-hung sash with stone lintels and sills. Addition on north with walls taller than the original building has stone coping. Wrought iron fence in front; parking on south and rear. CONTINUED? YES X NO			ASSOCIATED BUILDINGS? YES X NO TYPE: IF INVENTORIED, LIST ID NOS.:



ARCHITECT:

Louis A. Simon, Supervising Arc.

SOURCE: Cornerstone

BUILDER/CONTRACTOR:
Wickes Engineering & Const.

SOURCE:

Hist. & Arch. Signif. Survey

STATE ID NO.: 5AH281

ORIGINAL OWNER:

U.S. Treasury Department

SOURCE:

Hist. Arch. Significance Survey

THEME(S):

Colorado Town Form in Early Auto

Era, 1920-45

CONSTRUCTION HISTORY (DESCRIPTION, NAMES, DATES, ETC., RELATING TO MAJOR ALTERATIONS TO ORIGINAL STRUCTURE):
Lobby has limestone wainscoating. In 1950, an addition to the north side of the building was completed. The mural is now located in Littleton's city council chambers.

CONTINUED

YES

X NO

HISTORICAL BACKGROUND (DISCUSS IMPORTANT PERSONS AND EVENTS ASSOCIATED WITH THIS STRUCTURE):
This building was erected in 1939 at a cost of \$53,000 utilizing Works Progress Administration funds. The building was

built by the U.S. Treasury Department, with Louis A. Simon listed as supervising architect and Neal A. Melick, supervising engineer. It was one of 408 post offices built by the federal government during the 1930s and was the major public works project of the Depression era in Littleton. A major feature of the interior was a large mural painted by WPA artist John Fraser, who drew inspiration from issues of the Littleton Independent for his work. Fraser won a nationwide competition with his mural, "Littleton, Colorado," which was featured in Life magazine. In 1948, the mural was referred to as Littleton's "only nod to public art." The post office served Douglas, Jefferson, and Arapahoe county residents with three rural routes, a star route, a mounted city route, and two city carriers by 1948. In 1950, a large addition was added to the north to meet expanded needs of the facility.

CONTINUED

YES

X NO

SIGNIFICANCE (CHECK APPROPRIATE CATEGORIES AND BRIEFLY JUSTIFY BELOW):

ARCHITECTURAL SIGNIFICANCE:

REPRESENTS THE WORK OF A MASTER POSSESSES HIGH ARTISTIC VALUES

X REPRESENTS A TYPE, PERIOD, OR METHOD OF CONSTRUCTION

HISTORICAL SIGNIFICANCE

ASSOCIATED WITH SIGNIFICANT PERSONS

ASSOCIATED WITH SIGNIFICANT EVENTS OR PATTERNS

CONTRIBUTES TO AN HISTORIC DISTRICT

STATEMENT OF SIGNIFICANCE:

This building is associated with the history of mail service in Littleton, having been erected in 1939 as the post office and continuing in that role today. The building is also associated with Depression era public works projects, having been erected with WPA funds. The building, although altered, represents the Colonial Revival style in its gabled roof with center cupola, symmetrical facade with evenly spaced multi-light double-hung sash windows, and elaborated entrance.

CONTINUED

YES

X NO

REFERENCES (BE SPECIFIC):

Littleton Historical Museum files, Photograph Collection, #1382; Littleton Independent, 20 Aug. 1948 and 12 Apr. 1985; Historic, Architectural & Archeological Significance Survey form, Littleton Main Post Office, 1984.

CONTINUED

YES

X NO

SURVEYED BY: R.L. Simmons/T.H. Simmons

AFFILIATION: Front Range Research Associates, Inc.

DATE: October 1997